

## US EVA 10 (ALPHA) SUMMARY TIMELINE

PET HR : MIN	IV	US EVA 10 (ALPHA) EV1 – Wt	EV2 – Mk	PET HR : MIN
00:00	IV: Orbiter S-band inhibits √MCC-H GO for SSPTS cable demate  √MCC-H GO for PMA2/Lab umbilical demate  √MCC-H GO for Lab CETA light remove          √MCC-H GO for Russian power reconfig          EVA = 6:35	<u>POST DEPRESS</u> (00:05)	<u>POST DEPRESS</u> (00:05)	00:00
		<u>EVA 5 EGRESS/SETUP</u> (00:35)	<u>EVA 5 EGRESS/SETUP</u> (00:35)	
		<u>SSPTS CABLE STOW</u> (00:20)	<u>SSPTS CABLE STOW</u> (00:20)	
01:00		<u>PMA2/LAB UMBIL STOW</u> (00:40)	<u>PMA2/LAB UMBIL STOW</u> (01:00)	01:00
		<u>LAB CETA LIGHT</u> (00:45)		
02:00		<u>TEMP STOW N2 STBD TRAY AVIONICS</u> (00:45)	<u>TEMP STOW N2 PORT TRAY AVIONICS</u> (01:10)	02:00
03:00		<u>NODE 2 PDGF HORSESHOE CONNECTOR</u> (00:30)	<u>RPCM S0 4B-C R&amp;R</u> (00:30)	03:00
		<u>REMOVE AND STOW ACBM COVER, CBM SURVEY</u> (00:50)	<u>REMOVE AND STOW ACBM COVER, CBM SURVEY</u> (00:50)	
04:00				04:00
		<u>MATE S0/N1 SM POWER CABLE</u> (00:40)	<u>CONFIGURE PMA1/FGB H-JUMPERS</u> (00:50)	
05:00		<u>BSP RETRIEVE</u> (01:00)		05:00
			<u>VTE BAG RELOCATE</u> (00:25)	
			<u>NODE 2 HANDRAIL INSTALL</u> (00:25)	
06:00		<u>EVA 5 CLEANUP/INGRESS</u> (00:20)	<u>EVA 5 CLEANUP/INGRESS</u> (00:20)	06:00
		<u>PRE-REPRESS</u> (00:05)	<u>PRE-REPRESS</u> (00:05)	

## PRE US EVA 10 (ALPHA) TOOL CONFIG

### EV1

#### EMU D-rings

- ☒ 2 – Tether Extender
- ☒ 2 – Waist Tethers
- ☒ 1 – 85-ft Safety Tether on Left D-ring ext

#### MWS

- ☒ Small trash bag [right inside w/wire tie]
- ☒ 1 – Adj tether [left]
- ☒ 1 – RET (with PIP pin) [left]
- ☒ 2 – RET (sm-sm) [right]
- ☒ 2 – Wire ties
- ~~☒ Socket caddy [left inside]~~
- ☒ Swing Arm [right side]
  - ☒ PGT S/N \_\_1\_\_
    - (B1, CW2, 30.5)
    - ☒ 7/16-6 in ext
    - ☒ 1 – RET (sm-sm)
  - ☒ Wire Tie Caddy
    - ☐ 1 – long wire tie
    - ☒ 1 – RET (sm-sm)
- ☒ BRT [left side]
  - ☒ 2 – long wire ties tied together
  - ☒ 2 – short wire ties
  - ☒ 1 – RET (sm-sm)
- ☒ SAFER
- ☒ 1 - Pair of over-gloves
  - ☒ GP caddy

#### Items remain in the A/L

Prior to EVA, inspect:  
 RET cord for damage  
 Small trash bag bristles for damage or deformation  
 Safety & waist tether load alleviating straps: no red

Total RETs sm-sm used – 14  
 Total RETs with PIP pin – 3  
 Total RETs Lg-sm – 4  
 Total Adj tethers – 2 (+1 on trash bag)

### EV2

#### EMU D-rings

- ☒ 2 – Tether Extender
- ☒ 2 – Waist Tethers
- ☒ 1 – 85-ft Safety Tether on Left D-ring ext

#### MWS

- ☒ Small trash bag [right inside w/wire tie]
- ☒ 1 – RET (with PIP pin) [left]
- ☒ 2 – RET (sm-sm) [right]
- ☒ 2 – Wire ties
- ☒ Swing Arm [right side]
  - ☒ PGT S/N \_\_5\_\_
    - (B1, CCW1, 30.5)
    - ☒ 7/16-6 in ext
    - ☒ 1 – RET (sm-sm)
  - ☒ Wire Tie Caddy
    - ☒ 1 – RET (sm-sm)
- ☒ BRT [left side]
  - ☒ 2 – long wire ties tied together
  - ☒ 2 – short wire ties
  - ☒ 1 – RET (sm-sm)
- ☒ SAFER
- ☒ 1 - Pair of over-gloves
  - ☒ GP caddy

### CREWLOCK

- ☒ 1 - RET (Lg-sm)
  - ☒ C/L bag #4
    - ☒ Adj tether on outside
    - ☐ EVA Camera and Bracket
    - ☒ Fish stringer (w/free hook outside door on soft handle, on int)
    - ☒ Lab Caps (8) – J101 (15), J102 (15), J103 (17), J104 (15), J105 (15), J106 (21), J115 (25), J117 (25)
    - ☒ MMOD T-tool (int)
    - ☒ Int hook outside door for H-jumper
    - ☒ Round Scoop (on RET)
      - ☒ 1 – RET (sm-sm)
- ☒ 1 - RET (Lg-sm) – used later for ACBM cover
  - ☒ APFR 8 (w/ ingress aid)
- ~~☒ 1 - RET (Type – crew preference)~~
- ~~☒ APFR 5 (no ingress aid) – if volume allows~~

### CREWLOCK (cont)

#### ☒ Staging Bag

- ☒ Fuse Tether (1)
- ☒ Connector Cleaner Tool Kit
- ~~☒ Wire Tie Caddy (w/ 9 wire ties)~~
- ☒ PGT (spare) S/N \_\_8\_\_
  - ☒ PGT Battery S/N \_\_8\_\_
- ☒ Connector Pin Straightener
- ☒ Probe
- ☒ Velcro/Tape Caddy
- ☒ Pry Bar
- ☒ Vise Grips
- ☒ 3" scraper {from solar array cont C/L bag}

#### ☒ IV Bag

- ☒ Contamination Detection Kit
- ☒ Gold Salt Coupon (6)
- ☒ Color Chart (2)
- ☒ ISS Contamination Sampler (2)
- ☒ Ammonia Draeger Tube (11)
- ☒ DCM Plug (2) - SAFER Hard Mount
- ☒ GP Caddy (2)
  - ☒ Thermal Mittens (2 pr)
- ☒ EVA Ratchet
- ☒ Socket Caddy
  - ☒ 1/2 x 8-in socket (IV Hatch)
  - ☒ 7/16 x 6-in socket (backup)

#### ☒ Small ORU Bag

- ☒ Wire tie (2) sm ORU bag to C/L bag #4
- ☒ Adj tether to secure sm ORU bag to C/L bag #4
- ☒ RPCM (verify protective caps removed)
  - ☒ RET (sm-sm) (gate pointed away from RPCM)
- ☒ RET (sm-sm)

## PRE US EVA 10 (ALPHA) TOOL CONFIG

### CREWLOCK (cont)

☒ 1 - RET (Lg-sm)

☒ 6B Box Cover (BSP)

☒ 1 – Adj tether

☒ Dummy box

☒ 1 – RET (sm-sm)

☒ 1 – RET (Lg-sm)

~~☒ Med ORU Bag (for CETA Light once removed)~~

~~☒ 1 – RET (with PIP pin)~~

☒ 1 – RET (Lg-sm) (for Node 2 Shower Cap)

☒ 1 – Lg-sm RET

☒ Node 2 Handrail 0371

# US EVA 10 (ALPHA) PRE BRIEF

## EVA PREP:

- \* Follow procedures carefully
- \* PBA and SCU are pure O2
- \* Do not force connections

## A/L CONFIG and TOOLS:

- \* Crew lock bag for contingencies stays in the A/L
- \* ORU bag for CETA light stow will stay in the A/L

## EGRESS PLAN:

- \* EV2 to A/L D-ring extender; EV1 R waist to EV2 safety tether
- \* EV1 egresses and attaches own safety tether to A/L, EV2 attached to base of CETA spur handrail
- \* EV2 hands out APFRs; attaches crew lock bag wire-tied to sm ORU bag to self, (Large-small RETs stay in the A/L attached to tether extender)
- \* EV2 closes thermal cover
- \* Both check SAFER handles down and down

## TRANSLATION:

- \* EV1 fairleads stbd of EV2 CETA rail or CETA cart translation path
- \* Watch presence of MT and CETA carts now at WS 4
- \* Check tethers often
- \* Check each other's tethers, when possible
- \* Awareness of sensitive hardware in your work area (bend radii on cables, SHUTTLE)
- \* Review translation paths (DOUG/photos and MSG [16-0236](#))

## TETHERS and TOOLS:

- \* Follow good tethering protocol on all tools – “Good RET”
- \* Pull test everything (PGT sockets, APFRs, etc)

## GLOVE CHECKS:

- \* Before/after pre-determined tasks, day/night cycles
- \* Especially careful inspection of thumb/forefinger

## SSPTS and PMA Cables:

- \* Monitor cable bend radii
- \* Make sure FRGF and stovepipe/PMA interface clear when complete
- \* Report connector status after de-mating
- \* Minimize translation on the stovepipe
- \* Reference [MSG 16-0257 pg 11](#)

## Avionics Tray Cable Stowage:

- \* Monitor cable bend radii
- \* Report connector status after de-mating
- \* Review MSG 16-0034

## Gap Spanners:

- \* Ensure cables clear
- \* “Skid” 180 deg to loosen

## CETA Light:

- \* Remove/stow in A/L ORU bag

## ACBM Cover Removal and Stow:

- \* Good comm to ensure that we have appropriate control
- \* Reference [MSG 15-1453 & 16-0257 pg 12 & 13](#)

## Horseshoe Connectors:

- \* EV1 slide receptacles out, retrieve connectors, slide on; drive bolt
- \* Horseshoe connectors only on via micro-square soft capture
- \* Reference PDGF data package sent up ([MSG 16-0235 & 16-0257 pg 6 - 10](#))

## H-jumper:

- \* Description of de-mates (review labeling)
- \* No longer need to move bail back on PMA side
- \* Review briefing package (MSG 16-0034 & [16-0257 pg 14](#))

## RPCM:

- \* Standard R&R – ensure hook is on correctly (check IV)
- \* Check type and serial number of RPCM before removing

## BSP Remove:

- \* Don't stow hardware near radiator behind BSP
- \* Ensure forward lip of BSP interfaces with cover

## VTE Bag Relocate:

- \* Grab outboard bag

## Node 2 Handrail Install:

- \* Verify pre-install config, and follow installation direction arrow

## COMM PROTOCOL:

- \* Give IV status during work and when complete
- \* Give IV status on location during translation

## SUIT MAL PROTOCOL:

Challenge-response led by IV or nominal suit

## CONNECTORS:

- \* Check pin straightness
- \* No FOD in receptacle
- \* Good EMI band
- \* Proper bend radius

## PGT OPS:

- \* Check settings with IV
  - \* Pull test on all socket installs
  - \* Report Turn count
  - \* Report lights and actual torque from PGT display
- Red light – Low torque, green light – in torque window, Both – Hi torque  
Cal Procedure – Ratchet Collar – Not motor, Speed Collar – Cal, Pull trigger

## DAY/NIGHT TRANSITIONS: (IV will call)

- \* Lights, visor, glove heaters, check all tools secure, adjust suit temp if desired

## INGRESS PLAN:

- EV2 in first, then tether to D-ring extender
- EV1 disconnect EV2 safety tether, connect it to right waist tether
- EV1 disconnect own safety tether
- EV1 in feet first with an EV2 assist
- Check hatch seal clear before closing

## US EVA 10 (ALPHA) EVA INHIBIT PAD

### Ground

#### All EVAs

Ground Radar  
MCC-H 1. √TOPO console, ground radar restrictions in place for EVA

### USOS (1)

#### ALL EVAs

##### PCU

#### NOTE

PCUs may require up to 1 hr warm-up period before they are operational

MCC-H 1. √PCUs (two) operational in discharge mode and one of the following:  
a. CCS PCU EVA hazard control enabled  
b. No more than two arrays unshunted  
c. No more than two arrays pointed < 90° from velocity vector

OR

2. One or no PCUs operational in discharge mode and one of the following:  
a. No more than two arrays unshunted  
b. No more than two arrays pointed < 90° from velocity vector

#### LOCATION DEPENDENT INHIBITS

##### Lab Window

{EVA crew expected to be in this area during translation on Lab}

IV 1. Close window shutter

##### KU-BAND (SGANT) Antenna

{On call, EV crew not expected to be in this area}

MCC-H If EV crew < 3.3 ft from KU-BAND antenna

1. Park KU-BAND:
  - 1.1 Pointing Mode – Inhibit
  - 1.2 PLC – Reset
  - 1.3 Autotrack Continuous Retry – Inhibit

### USOS (2)

#### LOCATION DEPENDENT INHIBITS

##### S-BAND (SASA) ANTENNAS

{On call, EV crew not expected to be in this area}

MCC-H If EV crew < 3.6 ft from S1 SASA [P1 SASA]

1. P1 SASA [S1 SASA] – Active
2. S1 SASA [P1 SASA] – Powered down

##### SARJ

{On call, EV crew not expected to be in this area}

MCC-H If EV crew working within 2 ft or outboard of SARJ:

1. √DLA (1) – LOCKED
2. All motor setpoints set to zero
3. All motors deselected

OR

4. Both DLAs – LOCKED

#### EVA 5 SPECIFIC INHIBITS

##### SSPTS CABLE DEMATE

{Expect inhibits in place prior to egress}

MCC-H

1. RPCM Z13B A RPC 2 – Open, Close Cmh Inh
2. RPCM Z14B A RPC 2 – Open, Close Cmh Inh
3. RPCM LA2A3B D RPC 1 – Open, Close Cmh Inh
4. RPCM LA1A4A D RPC 3 – Open, Close Cmh Inh
5. DDCU LA1A OR LA4A CONVERTER – Off
6. DDCU LA2A OR LA3B CONVERTER – Off

##### PMA2 TO LAB UMBILICAL DISCONNECT

{Expect inhibits in place prior to egress}

MCC-H 1. RPCM LA1B C RPC 1 – 14 – Open, Close Cmd Inh

## US EVA 10 (ALPHA) EVA INHIBIT PAD

### USOS (3)

#### EVA 5 SPECIFIC INHIBITS

##### LAB CETA LIGHT REMOVE

{Expect inhibits in place just prior to task (starts 01:15 thermal clock)}

MCC-H      1. RPCM S01A C RPC 15 – Open, Close Cmd Inh  
              2. RPCM S02B C RPC 15 – Open, Close Cmd Inh

##### LAB TRAY AVIONICS RELEASE

{Expect inhibits in place prior to egress}

MCC-H      1. MBSU 1 RBI 10 & 11 – Open, Close Cmd Inhibit  
              2. MBSU 2 RBI 3 & 10 – Open, Close Cmd Inhibit  
              3. MBSU 3 RBI 2 & 3 – Open, Close Cmd Inhibit  
              4. MBSU 4 RBI 2 & 10 – Open, Close Cmd Inhibit  
              5. RPCM S01A\_D RPC 2, 4 & 5 – Open, Close Cmd Inhibit  
              6. RPCM S02B\_D RPC 2, 4 & 5 – Open, Close Cmd Inhibit  
              7. RPCM S03A\_C RPC 1 & 2 – Open, Close Cmd Inhibit  
              8. RPCM S04B\_C RPC 3 & 4 – Open, Close Cmd Inhibit

##### BSP REMOVAL

{Expect inhibits in place just prior to task}

MCC-H      1. RPCM Z14B B RPC 4 – Open, Close Cmd Inh  
              2. RPCM Z13B B RPC 4 – Open, Close Cmd Inh

##### S0/N1 SM POWER CABLE INSTALL/H-JUMPER REMOVAL

{Expect inhibits in place just prior to task}

MCC-H      1. RPCM Z14B A RPC 1 – Open, Close Cmd Inh  
              2. RPCM Z14B A RPC 3 – Open, Close Cmd Inh  
              3. MBSU 2 RBI 5 – Open, Close Cmd Inh  
              4. MBSU 3 RBI 5 – Open, Close Cmd Inh  
              5. MBSU 4 RBI 5 – Open, Close Cmd Inh

##### RPCM REMOVE AND REPLACE

{Expect inhibits in place during EVA, once SSRMS ready}

MCC-H      1. DDCU S14B Converter – OFF

### RSOS (1)

#### ALL EVAs

##### SM Antennas

IV            1. GTS – Deactivate  
              2. ARISS – Deactivate or VHF (144-146 MHz) TX only

##### FGB Antennas

MCC-M      1. ARISS – Deactivate  
              2. √FGB KURS P [KYPC P] – Deactivate

##### Soyuz Antennas

MCC-M      1. √Soyuz KURS A [KYPC A] – Deactivate

##### FGB Thrusters

MCC-M      1. √FGB MCS unpowered  
              2. √All FGB Attitude Control Thruster Valves (80) – closed  
              3. √FGB Attitude Control Manifold Valves – closed  
                    KШK1, KШK2, KШK4, KШK5, KШK9, OKO3, OKГ3, OKO6, OKГ6, OKO7, OKГ7, OKO8, OKГ8

##### Soyuz Thrusters

MCC-M      1. √Soyuz manifolds (4) – closed  
                    ЭКО1, ЭКО2, ЭКГ1, ЭКГ2  
              2. √Soyuz MCS unpowered  
              3. √Soyuz Attitude Control Thruster Valves (52) – closed  
              4. √Soyuz Main Engine Valves (K1,K2,K3,K4,K5,K6) – closed

## US EVA 10 (ALPHA) NOTES, CAUTIONS, AND WARNINGS

### NOTE

1. Bolt install: report torque and turns
2. Bolt release: report torque and turns if different from published range
3. EVA connectors: after disconnection and prior to connection; verify pin and EMI band integrity; verify connector free of FOD
4. Inspect QDs for damage prior to mating
5. Toolbox doors must be closed with one latch per door when EV crew not in immediate vicinity
6. MLI handholds are not rated for crewmember transition loads

### CAUTION

#### **ISS Constraints**

- A. Avoid inadvertent contact with
1. Grapple fixture shafts (drylube)
  2. PIP pins
  3. EVA Crane [PMA1]
  4. TCS Reflectors [PMA2,PMA3]
  5. APAS hardware [PMA2,PMA3]
  6. CETA Lights (Z-93 paint) [LAB,S1,Node 1]
  7. Passive UMAs
  8. MBS VDU, MCU, CRPCMs, and Cameras (taped radiative surfaces, silver Teflon)
  9. Deployed TUS cable
  10. S0 aft face Radiator
  11. GPS Antennas (S13 paint) [S0]
  12. UHF Antennas [LAB,P1]
  13. ETCS Radiators [S1,P1]
  14. EETCS/PV Radiator bellows and panels [P6,P4,S4]
  15. SASA RF Group [S1,P1]
  16. Heat pipe radiators [Z1]
  17. PCU cathode and HCA ports [Z1]
  18. Ku-Band Antenna (SGANT) dish [Z1]
  19. CMG cover/shells [Z1]
  20. SSRMS Cameras
  21. Open CBM petal covers and LAB window shutte

### CAUTION (Cont)

#### **ISS Constraints (Cont)**

- B. Electrical cables
1. Avoid bend radii < 10 times cable diameter
- C. Fiber optic cables
1. Avoid bend radii < 10 times cable diameter
  2. Avoid pulling on cable during mate/demate
- D. Fluid line flex hoses and QDs
1. Avoid bend radii < 5 in for hoses with diameter < 1 in on LAB, S0, S1, P1, and 10-in for hoses with diameter < 1 in on all other elements
  2. Avoid bend radii < 14 in for hoses with a diameter ≥ 1 in
  3. Additional care should be taken to not exceed bend radii when applying loads at the flexible hose to rigid tube stub interfaces
  4. Ensure fluid QD booties are fully closed prior to leaving worksite; wire tie if reqd
- E. For structural reasons
1. Avoid vigorous body motions, quick grabs and kickoffs against tether restraints
  2. Avoid performing shaking motions (sinusoidal functions) more than four cycles
  3. Avoid kicking S1/P1 radiator beam  
If any of these occur, wait 2 to 5 min to allow structural response to dissipate

## US EVA 10 (ALPHA) NOTES, CAUTIONS, AND WARNINGS

### CAUTION (Cont)

#### **ISS Constraints** (Cont)

##### F. Other

1. ITT Cannon connector: On demated connectors, do not rotate collar or manipulate cable/connector using collar or connector tool
2. WIS Antennas: do not use as handholds [Node 1,P6,Z1]
3. Lubricant from Ku-Band SGANT gimbals [Z1], CMGs [Z1], and RTAS Ground Strap fasteners [P6,P4,S4] can contaminate EMU
4. MLI handholds are not rated for crewmember translation loads
5. CBM petal covers may not be used as handholds unless both launch restraint pins are engaged

## US EVA 10 (ALPHA) NOTES, CAUTIONS, AND WARNINGS

### WARNING

#### ISS Constraints

##### A. Avoid inadvertent contact with

1. Grapple fixture targets and target pins
2. SSU, ECU, beta gimbal platform, mast canister, SAW blanket boxes unless the beta gimbal is locked and the motor is turned off
3. Stay inboard of SARJ when active
4. Stay 2 ft from S1/P1 radiator beam rotational envelope when beam is free to rotate
5. Stay 5 ft from moving MT on face 1

##### B. Handrails

1. Handrails previously used for MISSE attachment may not be used as a safety tether point [A/L endcone 564 & 566, A/L Tank 2 nad/fwd & port/fwd, P6 5389]

##### C. Pinch

1. NZGL connector linkage. Use caution when mating/locking
2. ITT Cannon Connector rotating housing
3. EV side of IV Hatch during Hatch operation (also snag hazard) [A/L]
4. LAB window shutter and CBM petal cover linkages during operation

##### D. QDs

1. If QD is in FID when valve is opened (bail fwd), QD will leak and fluid line may whip
2. Do not rotate if in mated/valve open config

### WARNING (Cont)

#### ISS Constraints (Cont)

##### E. RF radiation exposure

1. Stay 3.6 ft from S-Band (SASA) high gain Antenna when powered [S1,P1]
2. Stay 1.3 ft from S-Band (SASA) low gain Antenna when powered [S1,P1]
3. Stay 1 ft from UHF Antenna when powered [LAB, P1]

##### F. Sharp Edges

1. Inner edges of WIF sockets
2. Mating surfaces of EVA connectors. Avoid side loads during connector mating
3. Back side of MMOD shield fasteners
4. Spring loaded captive EVA fasteners (e.g., 6B-boxes, BMRRM); the end of the spring may protrude
5. PMA umbilical launch restraints-exposed bolt threads
6. Adjustable Fuse Tether (Fish Stringer) buckles stowed in Node Bag
7. Nickel coated braided copper Ground Straps may contain frayed wires [P6,P4,S4,S6]
8. Z1 handrail 6061 by the Ku-Band boom launch restraint [Z1]
9. Solar Array Blanket Box [P4,S4,P6]
10. Keep hands away from SSRMS LEE opening, and snares
11. Fastener threads on back of Z1 U-jumper male FQD panel, if nutplate cap missing

### WARNING (Cont)

#### ISS Constraints (Cont)

##### G. Thermal

1. EVA connectors with booties may become hot if left uncovered. Handling may need to be limited
2. PMA handrails may be hot. Handling may need to be limited
3. Turn off glove heaters when comfortable temp reached to prevent bladder damage. Do not pull fingers out of gloves when heaters are on
4. Uncovered trunnion pins may be hot
5. SSRMS/MBS operating Cameras and lights may radiate large amounts of heat
6. Stay 1 ft away from PMAs and MMOD shields > 270 degF if EMU sun visor up
7. Stay at least 1 ft away for no more than 15 min from PMAs and MMOD shields > 300 degF if EMU sun visor up
8. Stay 0.5 ft away from PMA and MMOD shields > 325 degF
9. Do not touch EMU protective visor if temp has been < -134 for > 15 min
10. No EMU TMG contact of PMAs and MMOD shields when temp > 320 degF
11. No EMU boot contact with foot restraint when temp < -120 degF or > 200 degF

##### H. Electrical Shock Hazard

1. Stay  $\geq 2$  ft from following ungrounded floating connectors if not inhibited: SSPTS on Lab fwd and stbd Node 1, H-jumper on FGB, MT cables, and S0 Bay 00, 02, and 03

## US EVA 10 (ALPHA)

### US EVA 10 (ALPHA) A/L EGRESS AND SETUP (00:35)

IV	EV1 – Wt (FF)	EV2 – Mk (FF)
1. Post crew egress: WVS Software: Select page – RF Camera sel ‘Advanced controls’ S-Band level (two) – max	<u>INITIAL CONFIG</u> 1. Verify: <input type="checkbox"/> Left waist tether connected to EV2’s 85-ft safety tether <input type="checkbox"/> hook locked <input type="checkbox"/> Over-gloves donned	<u>INITIAL CONFIG</u> 1. Verify: <input type="checkbox"/> Right waist tether to A/L D-ring Extender; √hook locked <input type="checkbox"/> 85-ft safety tether to EV1’s left waist tether <input type="checkbox"/> Over-gloves donned
	<u>EGRESS/INITIAL SET-UP</u> 1. Open hatch thermal cover 2. Egress crewlock 3. Attach own 85-ft safety tether to fwd A/L D-ring <input type="checkbox"/> √Gate closed <input type="checkbox"/> √Hook locked <input type="checkbox"/> √Reel unlocked 4. <del>Receive APFR 5 w/o ingress aid from EV2</del> 5. <del>Stow APFR onto stbd airlock toolbox (6, XX, F, 12)</del> 6. Receive APFR 8 w/ ingress aid; stow on BRT 7. Translate to CETA spur HR 3401 (base of CETA spur) 8. Attach EV2’s 85-ft safety tether to HR 3401 <input type="checkbox"/> √Gate closed <input type="checkbox"/> √Hook locked <input type="checkbox"/> √Reel unlocked 9. Give EV2 GO to release waist tether 10. Assist EV2 as reqd 11. Verify SAFER config <input type="checkbox"/> √L Handle down (MAN ISO Vlv – Open) <input type="checkbox"/> √R Handle down (HCM – Closed)	<u>EGRESS/INITIAL SET-UP</u> 1. <del>If present, transfer APFR 5 w/o ingress aid to EV1</del> 2. Transfer APFR 8 w/ ingress aid to EV1 3. Attach Lg-sm RET from APFR to A/L D-ring for ACBM cover 4. Egress crewlock 5. Retrieve sm ORU bag and crewlock bag combo from A/L 6. Stow bags on BRT 7. Attach Lg-sm RET from crewlock bag to A/L D-ring ext 8. On EV1 GO, release right waist tether, stow on self 9. Close hatch thermal cover 10. Verify SAFER config <input type="checkbox"/> √L Handle down (MAN ISO Vlv – Open) <input type="checkbox"/> √R Handle down (HCM – Closed)

## US EVA 10 (ALPHA)

### US EVA 10 (ALPHA) A/L EGRESS AND SETUP (00:35)

IV	EV1 – Wt (FF)	EV2 – Mk (FF)
	<p>12. Translate to Lab stbd SSPTS bag/Lab WIF via CETA spur, face 1 CETA rail, then stbd Lab strut path</p> <ul style="list-style-type: none"> <li>- Fairlead up CETA spur then stbd of CETA rail (~1/2 bay) or onto CETA carts if poor access</li> </ul> <p>13. Install APFR w/ ingress aid into Lab WIF 12 at 11, QQ, L, 12</p> <ul style="list-style-type: none"> <li>- Verify locking collar black-on-black</li> <li>- Perform pull test</li> </ul> <p>14. Continue translation to SSPTS bag</p> <p><del>15. Remove over-gloves; stow into sm trash bag (TBR)</del></p> <p>16. Perform glove inspection</p>	<p>11. Translate to Lab zenith SSPTS bag via CETA spur, then port Lab strut</p> <div data-bbox="1331 418 1990 561" style="border: 1px solid black; padding: 5px; margin: 10px 0;"> <p style="text-align: center;"><b>WARNING</b></p> <p style="text-align: center;">2' Keep Out Zone for floating cables between MT and MBS. Stay on UMA handrails during translation underneath MT</p> </div> <p><del>12. Remove over-gloves; stow into sm trash bag (TBR)</del></p> <p>13. Perform glove inspection</p>

# US EVA 10 (ALPHA)

## SSPTS CABLE STOW (00:20)

IV	EV1 – Wt (FF)	EV2 – Mk (FF)
<u>{SSPTS CABLE DEMATE INHIBITS</u> RPCM Z13B A RPC 2 – Open, Close Cmh Inh RPCM Z14B A RPC 2 – Open, Close Cmh Inh RPCM LA2A3B D RPC 1 – Open, Close Cmh Inh RPCM LA1A4A D RPC 3 – Open, Close Cmh Inh DDCU LA1A OR LA4A CONVERTER – Off DDCU LA2A OR LA3B CONVERTER – Off}	<u>TEMP STOW SSPTS BAG W9303 (STBD)</u> 1. Translate to Lab stbd SSPTS bag	<u>TEMP STOW SSTPS BAG W9302 (ZENITH/PORT)</u> 1. Translate to zenith port SSPTS bag 2. Temp stow crewlock bag near PMA2/Lab umbilical worksite using adjustable tether (HR 0263)
	<div style="border: 3px double black; padding: 5px; text-align: center;"> <b>WARNING</b>            Avoid unnecessary contact with Lab stovepipe. May present sharp edge hazard         </div>	
	<div style="border: 1px solid black; padding: 5px; text-align: center;"> <b>CAUTION</b>            Avoid with inadvertent contact with partially installed Lab MMOD shield (zenith/stbd, with NASA meatball)         </div>	
	2. Disconnect straps 1 and 2, wrapped around stove pipe bracket and connected to bag D-ring 3. Flip W9303 bag so that side A is up	3. Disconnect straps 1 and 2, wrapped around stove pipe bracket and connected to bag D-ring 4. Flip W9302 bag so that side A is up
	<div style="text-align: center;"> <b>NOTE</b>            Ensure safety tethers are not underneath SSPTS bag when flipped         </div>	
<input type="checkbox"/> √With MCC all inhibits in place for SSPTS cable demate 2. Give EV GO for SSPTS cable demate	4. Secure straps 1 and 2 to Lab HR 0296 fwd standoff 5. Move strap 4 from nadir end of HR 0274 to zenith 6. On IV GO, demate J16A from P16 7. Stow PMA cable with wire tie; verify bootie covering cable 8. Open side A of W9303 9. Stow cable in side A of W9303 (do no mate to cap) 10. Close side A of W9303 11. Perform glove inspection 12. Translate to PMA2/Lab umbilicals	5. Secure strap 1 to Lab HR 0264 aft standoff 6. Secure strap 2 to Lab HR 0263 fwd standoff 7. On IV GO, demate J3A from P3 8. Stow PMA cable in TA clamp (use wire tie if reqd); verify bootie covering cable 9. Open side A of W9302 10. Stow cable in side A of W9302 (do no mate to cap) 11. Close side A of W9302 12. Perform glove inspection 13. Translate to PMA2/Lab umbilicals

## US EVA 10 (ALPHA)

### SSPTS CABLE STOW – TASK DATA

**Tools:** None

**EVA Fasteners:** None

#### **EVA Connectors:**

Harness	From	To	Clamps (qty)	Conn Size	Function
J3A	P3	A side of W9302	N/A	25	Power – CH 1/4 to OPCU-2
J16A	P16	A side of W9303	N/A	25	Power – CH 2/3 to OPCU-1

**Foot Restraints:** None

#### **Timeline Considerations:**

**Notes:** None

**Cautions:** None

#### **Warnings:**

1. Minimize translational use of stove pipe brackets




Figure 2. SSPTS bag W9302 (zenith/port) temp stowed




Figure 1. SSPTS bag W9303 (stbd) temp

## US EVA 10 (ALPHA)

### SSPTS CABLE STOW – TASK DATA (Cont)




Figure 3. SSPTS Cable Routing When Connected to PMA2

## US EVA 10 (ALPHA)

### PMA2/LAB UMBILICAL STOW (01:00)

IV	EV1 – Wt (FF)	EV2 – Mk (FF)
<p><u>PMA2/LAB UMBILICAL DEMATE INHIBITS</u> RPCM LA1B C RPC 1-14 – Open, Close Cmd Inh</p> <p><input type="checkbox"/> √With MCC all inhibits in place for PMA2/Lab umbilical demate</p> <p>1. Give EV GO for PMA2/Lab umbilical demate</p>	<p><u>RELEASE PMA2 REDUNDANT UMBILICALS</u></p> <p style="text-align: center;"><u>NOTE</u> √Connectors for straight pins, no FOD, EMI band intact, and good bend radius Connector P613 has a missing rivet on the bail</p> <div style="border: 1px solid black; padding: 5px; text-align: center;"> <p><u>CAUTION</u> Avoid bend radii &lt; 10 times cable diameter; Avoid pulling on cable during mate/demate</p> </div> <p>1. Translate to PMA2</p> <p>2. Slide booties off all 8 connectors at Lab panel</p> <p>3. Wire tie into primary and redundant bundles if not already done</p> <p>4. On IV GO, release primary connectors from Lab panel:</p> <ul style="list-style-type: none"> <li><input type="checkbox"/> P611/J103 – primary (size 17)</li> <li><input type="checkbox"/> P613/J105 – primary* (NOTE: missing rivet) (15)</li> <li><input type="checkbox"/> P612/J106 – primary (21)</li> <li><input type="checkbox"/> P610/J117 – primary (25)</li> </ul> <p>5. Transfer primary umbilicals to EV5</p> <p>6. Release redundant connectors from Lab panel:</p> <ul style="list-style-type: none"> <li><input type="checkbox"/> P616/J101 – redundant (15)</li> <li><input type="checkbox"/> P615/J102 – redundant (15)</li> <li><input type="checkbox"/> P614/J 104 – redundant (15)</li> <li><input type="checkbox"/> P609/J115 – redundant (25)</li> </ul> <p>7. Verify tether clear of cables</p>	<p><u>RELEASE PMA2 REDUNDANT UMBILICALS</u></p> <p>1. Translate to PMA2</p> <p>2. Release wire ties as necessary, expect:</p> <ul style="list-style-type: none"> <li><input type="checkbox"/> Lab HR 0269</li> <li><input type="checkbox"/> Lab HR 0268</li> </ul> <p>3. Translate to crewlock bag</p> <p>4. Tether to and remove fish stringer with caps</p> <p>5. Temp stow fish stringer near umbilical worksite (suggest Lab HR 0269)</p> <p>6. Receive umbilicals from <del>EV4</del> EV1</p>

## US EVA 10 (ALPHA)

### PMA2/LAB UMBILICAL STOW (01:00) (Cont)

IV	EV1 – Wt (FF)	EV2 – Mk (FF)
<input type="checkbox"/> √With MCC all inhibits in place for disconnecting Lab avionics cables 2. Give EV GO for disconnecting Lab avionics cables	<p><u>STOW PMA2 REDUNDANT UMBILICALS</u></p> <ol style="list-style-type: none"> <li>1. Route redundant umbilical assy for temp stow on PMA2 (stbd/zenith side)</li> <li>2. Secure cables in clamps, as necessary               <ul style="list-style-type: none"> <li><input type="checkbox"/> C13 Clamp</li> <li><input type="checkbox"/> C12 Clamp</li> <li><input type="checkbox"/> C11 Clamp</li> <li><input type="checkbox"/> C10 Clamp</li> <li><input type="checkbox"/> C09 Clamp</li> <li><input type="checkbox"/> C08 Clamp</li> </ul> </li> <li>3. As necessary: use wire ties for additional restraint               <ul style="list-style-type: none"> <li><input type="checkbox"/> Recommend HR 0415 (zenith/stbd)</li> <li><input type="checkbox"/> Recommend HR 0416 (nadir/stbd)</li> <li><input type="checkbox"/> Recommend HR 0418 (stbd)</li> </ul> </li> <li>4. Verify harness clear of PMA2 CBM mating surface and grapple fixture; verify booties covering cables</li> <li>5. Perform glove inspection</li> <li>6. Translate to crewlock bag</li> <li>7. Retrieve round scoop from crewlock bag; stow on MWS</li> <li>8. Translate to Lab stbd avionics tray CETA light</li> </ol>	<p><u>STOW PMA2 PRIMARY UMBILICALS</u></p> <ol style="list-style-type: none"> <li>1. Route primary umbilical assy for temp stow on PMA2 (nadir/port side)</li> <li>2. Secure cables in clamps, as necessary               <ul style="list-style-type: none"> <li><input type="checkbox"/> C06 Clamp</li> <li><input type="checkbox"/> C05 Clamp</li> <li><input type="checkbox"/> C04 Clamp</li> <li><input type="checkbox"/> C03 Clamp</li> <li><input type="checkbox"/> C02 Clamp</li> <li><input type="checkbox"/> C01 Clamp</li> </ul> </li> </ol> <p><u>NOTE</u> Do not wire-tie umbilicals to stovepipe</p> <ol style="list-style-type: none"> <li>3. As necessary: use wire ties for additional restraint               <ul style="list-style-type: none"> <li><input type="checkbox"/> Recommend HR 0411 (nadir/port)</li> <li><input type="checkbox"/> Recommend HR 0412 (nadir/port)</li> <li><input type="checkbox"/> Recommend HR 0408 (zenith/port)</li> <li><input type="checkbox"/> Recommend HR 0403 (port)</li> </ul> </li> <li>4. Verify harness clear of PMA2 CBM mating surface and grapple fixture; verify booties covering cables</li> <li>5. Perform glove inspection</li> <li>6. Translate to fish stringer with caps</li> <li>7. Install caps (8) on Lab jacks: J101 (size 15) to J117 (size 25)                Zenith-most: <input type="checkbox"/> J101 (15) <input type="checkbox"/> J102 (15) <input type="checkbox"/> J103 (17) <input type="checkbox"/> J104 (15)                                  <input type="checkbox"/> J105 (15) <input type="checkbox"/> J106 (21) <input type="checkbox"/> J115 (25)                                  <input type="checkbox"/> J117:Nadir-most (25)             </li> <li>8. Tether to and restow fish stringer in crewlock bag</li> </ol> <p><u>INSTALL PORT FLUID TRAY GAP SPANNERS (PORT/FWD)</u></p> <ol style="list-style-type: none"> <li>9. Receive small trash bag with gap spanners from EV1</li> <li>10. On IV GO, demate P664, P665 in preparation for gap spanner installation</li> <li>11. Retrieve 2 – gap spanners from trash bag</li> <li>12. Install gap spanners from aft standoff of HR 0288, through avionics tray handrail to fwd standoff of HR 0259</li> <li>13. Translate to Lab port avionics tray</li> </ol>

## US EVA 10 (ALPHA)

### PMA2/LAB UMBILICAL STOW – TASK DATA

#### Tools:

EV1 (FF)	EV2 (FF)
Wire ties	Wire ties

**EVA Fasteners:** None

#### EVA Connectors:

Harness	From	To	Clamps	Size	Function
P609	J115	Temp stow		25	None
P610	J117	Temp stow		25	None
P611	J103	Temp stow		17	Data – RTDs, GNC Moding
P612	J106	Temp stow		21	Shell Heaters
P613	J105	Temp stow		15	Data – 1553 A, Video
P614	J104	Temp stow		15	Data – 1553 B, Video
P615	J102	Temp stow		15	None
P616	J101	Temp stow		15	Data – Audio

#### Foot Restraints:

Task	WIF	APFR Setting

#### Timeline Considerations:

#### Note:

1. Verify pin and EMI band integrity
2. Verify connector free of FOD
3. Do not wire-tie umbilicals to stovepipe

#### Cautions:

1. Avoid bend radii < 10 times cable diameter
2. Avoid pulling on cable during mate/demate

#### Warnings:

## US EVA 10 (ALPHA)

### PMA2/LAB UMBILICAL STOW – TASK DATA (Cont)




Figure 4. PMA2 umbilicals on STS-114




Figure 6. PMA2 umbilical routing to Lab

#### PMA 2 TO LAB CONNECTORS




Figure 5. PMA2-to-Lab connectors on Lab panel




Figure 7. Handrails for PMA2 Umbilical disconnect from Lab

## US EVA 10 (ALPHA)




Figure 8. Port Fluid Tray Gap Spanners




Figure 9. Stbd Fluid Tray Gap Spanners




Figure 10. Port/aft Gap Spanner

## US EVA 10 (ALPHA)

## LAB CETA LIGHT RETRIEVE (00:45)

[illegible]

## US EVA 10 (ALPHA)

### LAB CETA LIGHT RETRIEVE – TASK DATA

#### Tools:

EV1 (FF)	EV2 (FF)
PGT	
7/16-6 in ext	
Round Scoop	

#### EVA Fasteners:

Fastener Name	Label	Head Size	Qty	Release Torque (ft-lb)	Failure Torque (ft-lb)	Turns	RPM
CETA Light Stanchion Bolt	N/A	7/16	1	25.5 (max-34.7, due to thermal)	165.9	18-19.5	30

#### EVA Connectors:

Harness	From	To	Clamps	Size	Function
P101 (W9101)	CETA Light J101	Lab Tray J261	N/A	15	Sec Pwr 2B/1A
P102 (W9102)	CETA Light J252	Lab Tray J262	N/A	15	Sec Pwr 2B/1A

**Foot Restraints:** None

**Lab CETA Light Thermal Clock:** With no MLI bag, 1.25 hr from removal of heater power until transfer to airlock  
With MLI bag, 1.5 hr from removal of heater power until placement in bag, and 8 hr from placement in bag until transfer to airlock

#### Timeline Considerations:

#### Note:


#### Cautions:

1. CETA Light paint is sensitive. Avoid unnecessary contact

#### Warnings:

## US EVA 10 (ALPHA)

### LAB CETA LIGHT RETRIEVE – TASK DATA (Cont)





## US EVA 10 (ALPHA)

### TEMP STOW N2 TRAY AVIONICS UMBILICALS – TASK DATA SHEET

#### Tools:

EV1 (FF)	EV2 (FF)
Wire Ties	Wire Ties

**EVA Fasteners:** None

#### EVA Connectors:

Harness	From	To	Clamps	Size	Function
P670	J251	Temp Stow		25	Power to DDCU N2P2A
P671	J252	Temp Stow		25	Power to DDCU N202B
P672	J256	Temp Stow		25	Power to DDCU N2P3A
P673	J255	Temp Stow		25	Power to DDCU N203A
P674	J257	Temp Stow		25	Power to S0-1 MDM SDO card 6A Power to S0-2 MDM SDO card 8A Power to S0-2 MDM SDO card 8B
P101	J648	Temp Stow		15	Data Node 2 PDGF video 1
P102	J646	Temp Stow		25	Node 2 PDGF power 1
P103	J649	Temp Stow		15	Data Node 2 PDGF video 3
P104	J647	Temp Stow		25	Node 2 PDGF power 2
P105	J654	Temp Stow		15	Data Node 2 PDGF video 2
P662	J652	Temp Stow		25	Power to DDCU N2S4A
P663	J653	Temp Stow		25	Power to DDCU N2D4B
P660	J650	Temp Stow		25	Power to DDCU N2S1B
P661	J651	Temp Stow		25	Power to DDCU N2D1B
P665	J656	Temp Stow		13	Data Node 2 Port VSCA video
P664	J655	Temp Stow		25	Power to S0-2 MDM SDO card 6A Power to S0-1 MDM SDO card 8A Power to S0-1 MDM SDO card 8B

#### Timeline Considerations:

##### Note:

##### Cautions:

##### Warnings:

#### Foot Restraints:

TEMP STOW N2 AVIONICS UMBILICALS – TASK DATA SHEET (Cont)




Figure 12. Stbd Avionics Umbilical Connectors

TEMP STOW N2 AVIONICS UMBILICALS – TASK DATA SHEET (Cont)




Figure 13. Port Avionics Umbilical Connectors

## US EVA 10 (ALPHA)

### TEMP STOW N2 AVIONICS UMBILICALS – TASK DATA SHEET (Cont)




Figure 14. Port Avionics Tray





Figure 15. Handrails for Port Avionics Tray

# US EVA 10 (ALPHA)

## NODE 2 PDGF HORSESHOE CONNECTORS (00:30)

IV	EV1 – Wt (FF)												
<div></div> <div><div><input type="checkbox"/> Note: No inhibits required for Horseshoe connectors</div><div><div>1. Give EV1 GO for horseshoe connector demate</div><table><tr><th colspan="3">HORSESHOE CONNECTOR</th></tr><tr><th>Connector</th><th>Turns</th><th>Torque</th></tr><tr><td>P6/P8 (inboard)</td><td></td><td></td></tr><tr><td>P7/P5 (outboard)</td><td></td><td></td></tr></table></div></div>	HORSESHOE CONNECTOR			Connector	Turns	Torque	P6/P8 (inboard)			P7/P5 (outboard)			<div><div>HORSESHOE CONNECTOR MATES</div><div><div>1. Translate to Node 2 PDGF via Z1 fwd face (NOTE: EV2's safety tether also routed along this path)</div><div><div><input type="checkbox"/> Release fairlead at CETA rail</div><div><input type="checkbox"/> Fairlead self at Z1 HR 6025 only</div></div><div><div>WARNING</div><div>Avoid touching curvic coupling due to potential sharp edges</div></div><div><div>CAUTION</div><div>Avoid touching grapple pin and target</div></div></div><div><div>2. Release horseshoe connector receptacle MLI cover</div><div>3. Release horseshoe connector receptacle engagement bolt (two)</div><div>PGT, 7/16-6 in ext: A6, CCW2; 19 turns (to hardstop free spinning)</div><div><input type="checkbox"/> ✓Yellow band visible on both receptacles</div><div>4. Translate to horseshoe connector launch bracket</div><div>5. Release TA clamps as reqd (expecting 3)</div><div>6. Open MLI cover</div><div>7. On IV GO, rotate sq microfixtures (two) 60 deg ccw</div><div>8. Remove horseshoe connectors (P6/P8 first due to cable interference)</div><div>9. Install horseshoe connector onto PDGF</div><div>10. P6/P8 → J6/J8 (inboard)</div><div>11. Rotate square microfixture – LOCK, 60 deg cw</div><div>12. P7/P5 → J7/J5 (outboard)</div><div>13. Rotate square microfixture – LOCK, 60 deg cw</div><div>14. Drive horseshoe connector receptacle engagement bolt (two)</div><div>PGT, 7/16-6 in ext: A6, CW2; 15-19 turns (to hardstop)</div><div>15. Route cable through prepositioned wire-tie on HR 0335</div><div>16. Reinstall MLI cover, feeding horseshoe connector cables through opening created by flap in cover</div><div>17. Reinstall MLI cover over launch bracket</div><div>18. Install cable into empty TA clamps as reqd for appropriate cable length</div><div>19. Close any remaining open TA clamps</div><div>20. Translate to Node 2 fwd endcone (ACBM thermal cover)</div></div></div>
HORSESHOE CONNECTOR													
Connector	Turns	Torque											
P6/P8 (inboard)													
P7/P5 (outboard)													

## US EVA 10 (ALPHA)

### PDGF INSTALL ON NODE 2 – TASK DATA

#### EVA Tools:

EV1 (FF)	EV2 (FF)
PGT	MMOD T-tool
7/16-6 in ext	PGT
	7/16-6 in ext

#### EVA Fasteners:

Fastener	Head Size	Qty	Install Torque (ft-lb)	Release Torque (ft-lb)	Failure Torque (ft-lb)	Turns	RPM
PDGF EDF	7/16"	4	9.2 – initial 25.5 – final	25	100	Release: 5 turns at bolt Install: 4-6 total turns at bolt	10
PDGF Horseshoe Connector	7/16"	2		7.0-11.25	14.5	15-17 until yellow line visible 20 to hard stop	30

#### EVA Connectors:

Task	From	To	Clamps (Qty)	Conn Size	Function
P8/P6	Node 2	PDGF	2	---	Data/Power
P5/P7	Node 2	PDGF	2	----	Power/Data

#### Foot Restraints:

Task	WIF	APFR Setting
PDGF Install	Node2-08	2,QQ,C,12
PDGF Install – Backup	Node2-06	10, RR, H, 12

#### Cautions:

- Avoid touching grapple pin, connector area, underside of PDGF, target

#### Warning:

- Avoid touching curvic coupling due to potential sharp edges

## US EVA 10 (ALPHA)

### PDGF INSTALL ON NODE 2 – TASK DATA (Cont)





Figure 17. Node 2 PDGF Horseshoe Connectors Installed

### PDGF OVERVIEW



- – Cable Removed from TA Clamp
- ✗ – Cable Installed in TA Clamp

**RPCM S04B-C R&R (00:30)**

EVA/US EVA 10 (ALPHA)/FINAL REV A

## US EVA 10 (ALPHA)

### RPCM S04B-C R&R – TASK DATA

#### Tools:

EV1 (FF)	EV2 (FF)
	PGT
	7/16-6 in ext

#### EVA Fasteners:

Fastener Name	Head Size	Qty	Install Torque (ft-lb)	Release Torque (ft-lb)	Failure Torque (ft-lb)	Turns
RPCM Drive Screw	7/16	1	5.5 grnd 3.8 orbit	4.5	18.6 remv 8.5 install	8 rmv 6-7 install

**EVA Connectors:** None

**Foot Restraints:** None

#### ORU Identification:

	Serial Number
Spare RPCM	9938177
Failed RPCM	9000

#### RPCM Tether Orientation



#### Note:

1. Installation of tether on RPCM tether point must be oriented such that the hook gate is facing the body of the RPCM. Otherwise interference between the SPDA frame and the RPCM will not allow hook removal

#### Caution:

1. Failure to use wobble socket, or socket with equivalent outer diameter, to release lock springs can result in damage to the RPCM Drive Screw Assembly
2. Do not operate drive screw with scoop attached to microconical. The wobble socket feature will not extend thru the round scoop
3. Failure to align and fully seat socket until lock springs have released can result in damage to RPCM Drive Screw Assembly
4. Combined linear and rotational motion on the socket while inserting, can result in damage to RPCM Drive Screw Assembly

#### Warning:

1. RPCM may have sharp edges, use caution while handling



#### Thermal Clocks:

New RPCM in MLI bag – 6-hr transfer clock from removal from airlock to removal from bag  
 2-hr activation clock from removal from bag to physically installed

Old RPCM in MLI bag – 1.5-hr removal clock from physically removed to placement in MLI bag  
 8-hr transfer clock from placement in bag to placement in airlock

## US EVA 10 (ALPHA)

### RPCM S04B-C R&R – TASK DATA (Cont)



## US EVA 10 (ALPHA)

### REMOVE ACBM COVER, CBM SURVEY (00:50)

IV	EV1 – Wt (FF)	EV2 – Mk (FF)
<p>IV: Ref. Pg 41 for Node 2 Handrail install</p>	<p><u>REMOVE NODE 2 ACBM THERMAL COVER</u></p> <ol style="list-style-type: none"> <li>1. Translate to shower cap on ISS port end along zenith gap spanner</li> <li>2. Perform glove inspection</li> <li>3. Doff over glove; temp stow on self</li> <li>4. With EV2, fold shower cap in half</li> <li>5. With EV2, fold shower cap in half twice more; attaching wire ties as necessary</li> <li>6. Tether to shower cap</li> <li>7. Secure shower cap into final bundle; temp stow</li> <li>8. Visually inspect the Node 2 CBM to ensure that it is clear for PMA2 berthing</li> <li>9. Perform glove inspection</li> <li>10. If feasible, donn over gloves</li> <li>11. Translate to airlock w/ shower cap</li> <li>12. Stow shower cap inside airlock</li> <li>13. Close airlock hatch thermal cover</li> <li>14. Verify SAFER config               <ul style="list-style-type: none"> <li><input type="checkbox"/> √L Handle down (MAN ISO Vlv – Open)</li> <li><input type="checkbox"/> √R Handle down (HCM – Closed)</li> </ul> </li> <li>15. Translate to Node 1 fwd stbd/zenith endcone</li> </ol>	<p><u>REMOVE NODE 2 ACBM THERMAL COVER</u></p> <ol style="list-style-type: none"> <li>1. Translate to Node 2 endcone/shower cap via zenith crewlock, zenith/aft Node 1 and primary nadir/aft Node 2 handrail path</li> </ol> <p style="text-align: center;"><u>NOTE</u> Watch for CETA light on Node 1 port while translating</p> <ol style="list-style-type: none"> <li>2. Perform glove inspection</li> <li>3. Doff over glove; temp stow on self</li> <li>4. Release thermal cover Velcro strap in order to loosen from ACBM stove pipe</li> <li>5. Assist EV1; attaching wire ties as necessary</li> <li>6. Release thermal cover Dzus fasteners (at 3:00) using MMOD T-tool</li> <li>7. Secure shower cap into final bundle</li> <li>8. Visually inspect the Node 2 CBM to ensure that it is clear for PMA2 berthing</li> <li>9. Perform glove inspection</li> <li>10. Donn over gloves</li> <li>11. Assist EV1 with shower cap stow in airlock as required (if assisting, will need to unwind safety tether on way back)</li> <li>12. Translate to PMA1/FGB zenith face via aft/zenith Node 1</li> </ol>

## US EVA 10 (ALPHA)

### REMOVE ACBM COVER, CBM SURVEY – TASK DATA

#### Tools:

EV1 (FF)	EV2 (FF)
Wire Ties	Wire Ties
	MMOD T-tool

**EVA Fasteners:** None

**EVA Connectors:** None

**Connector Inhibits:** None

**Foot Restraints:** None

#### Timeline Considerations:

#### Note:

#### Cautions:

#### Warnings:




Figure 16. Node 2 ACBM Thermal Cover (Shower Cap)

## US EVA 10 (ALPHA)

### S0/N1 POWER CABLE/H-JUMPER HARNESS REMOVAL (00:50)

IV	EV1 – Wt (FF)	EV2 – Mk (FF)
<p><u>(S0/N1 POWER CABLE/H-JUMPER REMOVE INHIBITS</u>  RPCM Z14B A RPC 03 – Open, Close Cmd Inh  RPCM Z14B A RPC 01 – Open, Close Cmd Inh  MBSU 2 RBI 5 – Open, Close Cmd Inh  MBSU 3 RBI 5 – Open, Close Cmd Inh  MBSU 4 RBI 5 – Open, Close Cmd Inh}</p>	<p><u>MATE S0/N1 SM POWER CABLE/H-JUMPER REMOVE</u>  1. Translate to Node 1 fwd stbd/zenith endcode  2. <a href="#">Perform glove inspection</a>  3. <a href="#">If not already performed, doff over gloves</a></p> <p style="text-align: center;"><u>NOTE</u>  √Connectors for straight pins, no FOD, EMI band intact, and good bend radius</p> <p>4. Demate:  <input type="checkbox"/> Z1 P150 (W36C) from Node 1 J650  <input type="checkbox"/> S0 P651 (W4014) from Node 1 J651  5. <a href="#">Demate:</a>  <input type="checkbox"/> <a href="#">S0 P650 (W4012) from J871 on S0 swing arm</a>  6. <a href="#">Inspect and mate:</a>  <input type="checkbox"/> <a href="#">S0 P651 (W4014) onto J872 on S0 swing arm</a>  7. Un-wire tie S0/N1 SM Power Cable (W4020) from HR 1003L (S0 Tray H1) on S0 tray  8. Route SM cable and S0 P650 to Node 1 J651/J650  9. Remove cap from S0/N1 SM Power Cable P651A; stow in trash bag  10. Inspect and mate:  <input type="checkbox"/> S0 P650 (W4012) onto Node 1 J650  <input type="checkbox"/> SM Power Cable P651A to Node 1 J651  11. Cleanup cable as necessary</p> <p>12. Translate to Z1 stbd/nadir face (aft corner, nadir of WIF 02)  13. Inspect and mate:  <input type="checkbox"/> Z1 P150 (W36C) onto Z1 J650 (inboard)  14. Install in TA clamps as reqd (3 or 4)  15. Clean up cable slack as required  16. Perform WVS photo closeout of connectors  17. Perform glove inspection  18. <a href="#">Doff over gloves</a>  19. Translate to Airlock</p>	<p><u>PORT H-JUMBER REMOVAL (CHANNEL 1/4)</u>  1. Translate to PMA1/FGB zenith face via aft Node 1  2. Perform glove inspection  3. BRT to PMA HR 0004</p> <p>4. Slide back thermal booties to expose connectors from:  <input type="checkbox"/> H-Jumper: P16A, P17A  <input type="checkbox"/> FGB P16  <input type="checkbox"/> FGB P17  5. Attach RET to H-jumper  6. Demate connector:  <input type="checkbox"/> Jumper J17A from FGB P17  <input type="checkbox"/> Jumper J16A from FGB P16  <input type="checkbox"/> Jumper P17A from PMA1 J17  <input type="checkbox"/> Jumper P16A from PMA1 J16  7. Remove H-Jumper; stow on self via attached wire tie  8. Inspect and mate:  <input type="checkbox"/> FGB P17 to PMA1 J17  <input type="checkbox"/> FGB P16 to PMA1 J16  9. Perform WVS photo closeout of connectors  10. Re-install thermal booties  11. Perform glove inspection  12. Translate to temp stowed crewlock bag on Airlock via zenith/aft Node 1 path  13. Temp stow H-jumper on crewlock bag using exposed equipment hook  14. Translate to Airlock</p>

## US EVA 10 (ALPHA)

### S0/N1 POWER CABLE/H-JUMPER HARNESS REMOVAL – TASK DATA

#### Tools:

EV1 (FF)	EV2 (FF)

EVA Fasteners: N/A

#### EVA Connectors:

Harness	From	To	Size	Function	Inhibit
Z1 P150 (W36C?)	N1 J650	Z1 J650	25	Secondary Power to CHT 22	RPCM Z14B A 03 – Open, Close Cmd Inh
S0 P651 (W4014)	N1 J651	S0 swing arm J872	25	MBSU 2 Power to CHT 23 and 24	MBSU 3 RBI 5 – Open, Close Cmd Inh
S0 P650 (W40XX)	S0 swing arm J87??	N1 J650	25	Primary Power to CHTs 21 and 22	MBSU 2 RBI 5 – Open, Close Cmd Inh
S0/N1 Jumper P651A	Temp Stow	N1 J651	25	MBSU 4 Power to CHT 23 and 24	MBSU 4 RBI 5 – Open, Close Cmd Inh
H-Jumper J17A	FGB P17		25	Secondary Power to ARCUs 53 and 54	RPCM Z14B A 01 – Open, Close Cmd Inh
H-Jumper J16A	FGB P16		25	Secondary Power to CHT 21 Secondary Power to CHT 22	RPCM Z14B A 01 – Open, Close Cmd Inh RPCM Z14B A 03 – Open, Close Cmd Inh
H-Jumper P17A	PMA1 J17		25	Secondary Power to ARCUs 53 and 54, CHT 21	RPCM Z14B A 01 – Open, Close Cmd Inh
H-Jumper P16A	PMA1 J16		25	Secondary Power to CHT 22	RPCM Z14B A 03 – Open, Close Cmd Inh
FGB P17		PMA1 J17	25	Secondary Power to ARCUs 53 and 54	RPCM Z14B A 01 – Open, Close Cmd Inh
FGB P16		PMA1 J16	25	Primary Power to CHTs 21 and 22	MBSU 2 RBI 5 – Open, Close Cmd Inh

Foot Restraints: None

#### Timeline Considerations:

1. EV1 step 2 first box (demate Z1P150 from Node 1 J650), step 4 (demate S0 P650 from swing arm), step 8 first box (mate S0 P650 to Node 1 J650), and steps 10-14 (mate of Z1 P150 to Z1 J650) are part of the H-jumper removal task. The remainder of EV1 steps are the SM power cable install. These tasks are intermingled for time lining efficiency

#### Note:

2. Verify pin and EMI band integrity
3. Verify connector free of FOD

#### Cautions:

#### Warnings:

## US EVA 10 (ALPHA)

### S0/N1 POWER CABLE/H-JUMPER HARNESS REMOVAL – TASK DATA (Cont)




Figure 18. Installing Node 1 end of S0/N1 SM Power Cable into Node 1 J651




Figure 19: S0/N1 SM Power Cable



Figure 20. Node 1 J651

## US EVA 10 (ALPHA)

16-0034: 10A EVA 5: Answers to Peggy's Questions  
Page 5 of 12

### Current Configuration




Figure 21. Current configuration of S0/N1 SM Power Cable

16-0034: 10A EVA 5: Answers to Peggy's Questions  
Page 6 of 12

### Final Configuration





Figure 22. Final configuration of S0/N1 SM Power Cable

## US EVA 10 (ALPHA)

### S0/N1 POWER CABLE/H-JUMPER HARNESS REMOVAL – TASK DATA (Cont)



## US EVA 10 (ALPHA)

### BSP RETRIEVE / VTE BAG RELOCATE / NODE 2 HANDRAIL (01:00)

IV	EV1 – Wt (FF)	EV2 – Mk (FF)																											
<div><div><u>BSP RETRIEVE INHIBITS</u> RPCM Z14B B RPC 4 – Open, Close Cmd Inh RPCM Z13B B RPC 4 – Open, Close Cmd Inh}</div><div><div><input type="checkbox"/> √MCC-H GO to remove BSP</div><div>1. Give EV GO for BSP remove</div></div></div> <div><div>Dummy Box Bolt Data</div><table><tr><td>Bolt</td><td>Turns</td><td>Torque</td></tr><tr><td>Center Jack</td><td></td><td></td></tr><tr><td>Outer Fastener (Nadir)</td><td></td><td></td></tr><tr><td>Outer Fastener (Zenith)</td><td></td><td></td></tr></table></div> <div><table><tr><td></td><td colspan="2">Bolt 1 (left)</td><td colspan="2">Bolt 2 (right)</td></tr><tr><td>HR</td><td>Turns</td><td>Torque</td><td>Turns</td><td>Torque</td></tr><tr><td>0371</td><td></td><td></td><td></td><td></td></tr></table></div>	Bolt	Turns	Torque	Center Jack			Outer Fastener (Nadir)			Outer Fastener (Zenith)				Bolt 1 (left)		Bolt 2 (right)		HR	Turns	Torque	Turns	Torque	0371					<div><div><u>BSP REMOVAL</u></div><div><div>1. Retrieve 6B box cover with dummy box from A/L</div><div>2. Attach Lg-sm RET from cover to A/L D-ring ext</div><div>3. Translate to Z1 BSP (stbd)</div><div>4. Remove dummy box from 6B box cover; temp stow (suggest A/L HR 0522)</div><div>5. Open BSP thermal cover (“garage door”)</div><div>6. Tether to BSP tether point</div><div>7. BRT to HR 6001</div><div>8. On IV GO, release <b>BSP outer fasteners</b> (2) PGT, 7/16-6 in ext; A7, CCW2; 15 turns</div><div>9. Release <b>BSP center jack bolt</b> PGT, 7/16-6 in ext; A7, CCW2; 33 turns</div><div>10. Release BSP by sliding it along guide pins</div><div>11. Inspect BSP cotherm for damage</div><div>12. Inspect Z1 cold plate for cotherm debris</div><div>13. Stow BSP on 6B box cover; wrap with MLI cover</div></div><div><div><u>BSP DUMMY BOX INSTALL</u></div><div><div>14. Retrieve dummy box, install on Z1</div><div>15. Drive <b>BSP center jack bolt</b> PGT, 7/16-6 in ext; A7, CW2; ~25-30 turns to HS</div><div>16. Drive <b>BSP outer fasteners</b> (2) PGT, 7/16-6 in ext; A7, CW2; ~7-12 turns to HS</div><div>17. Close BSP thermal cover</div><div>18. Retrieve 6B box cover/BSP</div><div>19. Translate to Airlock</div></div></div></div>	<div><div><u>VTE BAG RELOCATE</u></div><div><div>1. Translate to zenith face of crewlock</div><div>2. Perform glove inspection</div><div>2. Tether to and remove VTE bag (outboard)</div><div>4. Translate to S0 face 3</div><div>5. Stow VTE bag on handrails 3425 (inboard standoff) and 3430 (2 straps to outboard standoff) (leave 4th strap free)</div></div><div><div><u>NODE 2 HANDRAIL INSTALL</u></div><div><div>6. Translate to Airlock</div><div>7. On MCC Go: Ingress Airlock</div><div>8. Retrieve Node 2 handrail from temp stow</div><div>9. Egress Airlock, close hatch thermal cover</div><div>10. Verify SAFER config:<div><div><input type="checkbox"/> √L Handle down (MAN ISO Vlv – Open)</div><div><input type="checkbox"/> √R Handle down (HCM – Closed)</div></div></div><div>11. √Handrail soft dock armed (push both buttons)</div><div>12. Install and soft dock handrail (arrow on bottom, align HR# to structure #, push in to soft dock)</div><div>13. Tighten <b>handrail bolts</b> (two) PGT, 7/16-6 in ext: A2, CW2; ~8 turns</div><div>14. Report turns and torque<div><div><input type="checkbox"/><input type="checkbox"/> HR 0371 inbrd end cone near WIF 07</div></div></div></div></div></div>
Bolt	Turns	Torque																											
Center Jack																													
Outer Fastener (Nadir)																													
Outer Fastener (Zenith)																													
	Bolt 1 (left)		Bolt 2 (right)																										
HR	Turns	Torque	Turns	Torque																									
0371																													

## US EVA 10 (ALPHA)

### BSP RETRIEVE – TASK DATA

#### Tools:

EV1 (FF)	EV2 (FF)
PGT	
7/16-6 in	
6B Box Cover	
Dummy Box	

#### EVA Fasteners:

Fastener	Label	Head size	Qty	Install Torque (ft-lb)	Release Torque (ft-lb)	Failure Torque (ft-lb)	Turns	RPM
BSP Outer Fasteners	N/A	7/16"	2	N/A	12.3	14.8	15	30
BSP Center Jacking	N/A	7/16"	1	N/A	12.3	14.8	33	30
Dummy Box Center Jacking	N/A	7/16"	1	9.2	N/A	13.2	24.5-29.5	30
Dummy Box Outer Fasteners	N/A	7/16"	2	9.2	N/A	13.2	7-12	30

**EVA Connectors:** None

#### Mass and Dimensions:

Item	Mass (lb)	Dimensions (in)

**Foot Restraints:** None

**BPS Thermal Clock:** 2 hr from removal of heater power until transfer to Airlock



#### Note:

#### Cautions:

#### Warnings:

## US EVA 10 (ALPHA)

### BASE BAND SIGNAL PROCESSOR (BSP)




## US EVA 10 (ALPHA)



## US EVA 10 (ALPHA)

### VENT TOOL EXTENDER BAG RELOCATE



Vent Tool Extender Bag Temp Stow – S0 Face 02

## US EVA 10 (ALPHA)

### US EVA 10 (ALPHA) CLEANUP AND INGRESS (00:20)

IV	EV1 – Wt (FF)	EV2 – Mk (FF)
1. Perform prior to ingress: WVS PWRDN (P/TV, <u>WVS CUE CARD</u> )	1. Translate to airlock 2. Perform glove inspection 3. Perform tool inventory 4. Transfer BSP to EV2 6. Translate to CETA spur HR 3401 7. On EV2 GO, disconnect EV2's safety tether; attach to own left waist tether <input type="checkbox"/> √Hooks locked (2) 8. Translate to airlock 9. Disconnect EV2's A/L safety tether from A/L; temp stow on self 10. Ingress airlock DCM 11. Retrieve SCU, remove DCM cover 12. Connect SCU to DCM, √Locked 13. Water – OFF 14. Hatch thermal cover – close 15. Secure thermal cover Velcro strap	1. Translate to airlock 2. Perform glove inspection 3. Retrieve crewlock bag from zenith side of toolbox 4. Perform tool inventory 5. Ingress airlock; stow crewlock bag 6. Receive BSP from EV1; stow on Lg-Sm RET in airlock 7. Connect right waist tether to UIA D-ring <input type="checkbox"/> √Hook locked 8. Give EV1 GO to disconnect EV2 safety tether DCM 9. Retrieve SCU, remove DCM cover 10. Connect SCU to DCM, √Locked 11. Water – OFF
	<div style="border: 1px solid black; padding: 5px; text-align: center;"> <b>CAUTION</b>            Do not close hatch until EMU water – OFF for 2 min         </div>	
	16. √EV Hatch clear of FOD and obstructions 17. EV Hatch – verify handle position per hatch decal; close and lock 18. Go to PRE REPRESS portion of {CREWLOCK DEPRESS/REPRESS CUE CARD} (SODF: ISS EVA SYS: EVA PREP/POST)	12. Go to PRE REPRESS portion of {CREWLOCK DEPRESS/REPRESS CUE CARD} (SODF: ISS EVA SYS: EVA PREP/POST)

## US EVA 10 (ALPHA)

### POST US EVA 10 (ALPHA) TOOL CONFIG

#### EV1

##### EMU D-rings

- ☐ 2 – Tether Extenders
- ☐ 2 – Waist Tethers
- ☐ 1 – 85-ft Safety Tether

##### MWS

- ☐ Small trash bag [right inside]
- ☐ 1 – Adj tether [right]
- ☐ 1 – RET (with PIP pin) [left]
- ☐ 2 – RET (sm-sm) [right]
- ☐ 2 – Wire ties
- ☒ ~~Socket caddy~~
- ☐ Swing Arm [right side]
  - ☐ PGT w/7/16-6 in ext
    - ☐ 1 – RET (sm-sm)
  - ☐ Wire Tie Caddy
    - ☐ 1 – RET (sm-sm)
- ☐ BRT [left side]
  - ☐ 2 – long wire ties tied together
  - ☐ 2 – short wire ties

- ☐ 1 – RET (sm-sm)

##### ☐ SAFER

- ☐ 1 - Pair of over-gloves
  - ☐ GP caddy

Total RETs sm-sm used – 14
Total RETs with PIP pin – 3
Total RETs Lg-sm – 4
Total Adj tethers – 3

#### EV2

##### EMU D-rings

- ☐ 2 – Tether Extenders
- ☐ 2 – Waist Tethers
- ☐ 1 – 85-ft Safety Tether

##### MWS

- ☐ Small trash bag [right inside]
  - ☐ MMOD T-tool
- ☐ 1 – RET(with PIP pin) [left]
- ☐ 2 – RET (sm-sm) [right]
- ☐ 2 – Wire ties
- ☐ Swing Arm [right side]
  - ☐ PGT w/ 7/16-6 in ext
    - ☐ 1 – RET (sm-sm)
  - ☐ Wire Tie Caddy
    - ☐ 1 – RET (sm-sm)
- ☐ BRT [left side]
  - ☐ 2 – long wire ties tied together
  - ☐ 2 – short wire ties
  - ☐ 1 – RET (sm-sm)

##### ☐ SAFER

- ☐ 1 - Pair of over-gloves
  - ☐ GP caddy

#### ADDITIONAL ITEMS RETURNED TO A/L

- BSP (cap connectors w/ caps in ziplock bag)
- H-Jumper
- Lab CETA Light
- Node 2 Shower Cap

##### ☐ 1 - RET (Lg-sm)

- ☐ C/L bag #4
  - ☐ H-jumper
  - ☐ Fish stringer (from caps)
  - ☐ EVA Camera and Bracket
  - ☐ Small trash bag (from gap spanners)
  - ☐ Adj tether (2)
  - ☐ RET (sm-sm) - previously on round scoop

#### CREWLOCK

- ☐ Staging Bag
  - ☐ 3" Scraper

##### ☐ IV Bag

- ☐ Contamination Detection Kit
  - ☐ Gold Salt Coupon (6)
  - ☐ Color Chart (2)
  - ☐ ISS Contamination Sampler (2)
  - ☐ Ammonia Draeger Tube (11)
- ☐ DCM Plug (2) - SAFER Hard Mount
- ☐ GP Caddy (2)
  - ☐ Thermal Mittens (2 pr)
- ☐ EVA Ratchet
- ☐ Socket Caddy
  - ☐ 1/2 x 8-in socket (IV Hatch)
  - ☐ 7/16 x 6-in socket (backup)

##### ☐ Small ORU Bag

- ☐ Wire-tied (2) to C/L bag #4
  - ☐ Adj tether to secure sm ORU bag to C/L bag #4
- ☐ RPCM (failed)
  - ☐ 2 - RET (sm-sm)

##### ☐ Lg-sm RET

- ☐ 6B box cover (BSP)
  - ☐ 1 – Adj tether
  - ☐ 1 – RET (sm-sm)
  - ☐ BSP

##### ☐ 1 – RET (Lg-sm) (previously holding APFR)

- ☐ Node 2 Shower Cap

##### ☐ 1 - RET (Lg-sm)

- ☒ ~~Med ORU Bag~~
- ☒ ~~1 – RET (with PIP pin)~~
  - ☐ Lab CETA Light (exposed jacks need to be taped once inside)
  - ☐ Round scoop

##### ☐ Lg-sm RET (previously holding Node 2 handrail)